

CAD -269- DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES - REGION III		DESIGNATION: BLLM No.176	
		PAGE: 76 / 99	
THE POINT IS MEASURED AND PERMANENTLY MARKED IN 2014 STA. ROSA CADASTRE		GEOGRAPHIC COORDINATES (WGS 84) Φ = N15°26'16.04566" λ = E120°53'13.90147"	
GEOGRAPHIC COORDINATES (OLD)		GEOGRAPHIC COORDINATES (PRS 92) Φ = N15°26'21.66589" λ = E120°53'09.07827"	
Φ =		λ =	
GRID COORDINATES (PTM-OLD) in Meter		GRID COORDINATES (PTM) in Meter N = 1707417.520 E = 487749.523	
N =		E =	
LOCAL COORDINATES (20000,20000) in Meter		ELEVATION in Meter	
X =		Y =	
		Above mean sea level 23.022	
		Ellipsoidal Height 24.551	
CONTROL POINT Bureau of Lands Location Monument (BLLM)			
ISLAND:	LUZON	CITY / MUNICIPALITY:	STA. ROSA
PROVINCE:	NUEVA ECIJA	BARANGAY:	INSPECTOR
DESCRIPTION: Mark is the head of a 3" copper nail embedded and centered on a 25X 25cm (top) by 35X35cm(base) by 120cm(height) standard concrete square base frustum, set on the ground with protruding 20 cm on the surface with inscriptions..."STA.ROSA NEJ BLLM NO.176, PB-03-000046 DENR III 2014".			
ACCESS: The monument is located beside the Barangay Hall of Inspector. It is about 550 meters from the Sta.Rosa-Tarlac Road.			
SURVEYED/ DESCRIBED BY:		DATE ESTABLISHED:	
GeoIDEx		April 28-May 17, 2014	
PHOTO / SKETCH			
			
For updates please rectify and return to DENR R3 LMS Office or fax to (045) 455-3402.			