

CAD -269- DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES - REGION III	DESIGNATION: BLLM No.177
	PAGE: 77 / 99

THE POINT IS MEASURED AND PERMANENTLY MARKED IN 2014 STA. ROSA CADASTRE	GEOGRAPHIC COORDINATES (WGS 84) $\Phi =$ N15°26'22.22972" $\lambda =$ E120°53'19.35925"
GEOGRAPHIC COORDINATES (OLD)	GEOGRAPHIC COORDINATES (PRS 92) $\Phi =$ N15°26'27.85022" $\lambda =$ E120°53'14.53620"
$\Phi =$ $\lambda =$	GRID COORDINATES (PTM) in Meter
GRID COORDINATES (PTM-OLD) in Meter	$N =$ 1707607.502 $E =$ 487912.335
$N =$ $E =$	ELEVATION in Meter
LOCAL COORDINATES (20000,20000) in Meter	Above mean sea level 23.293
$X =$ $Y =$	Ellipsoidal Height 24.836

CONTROL POINT
Bureau of Lands Location Monument (BLLM)

ISLAND:	LUZON	CITY / MUNICIPALITY:	STA. ROSA
PROVINCE:	NUEVA ECIJA	BARANGAY:	INSPECTOR

DESCRIPTION:
Mark is the head of a 3" copper nail embedded and centered on a 25X 25cm (top) by 35X35cm(base) by 120cm(height) standard concrete square base frustum, set on the ground with protruding 20 cm on the surface with inscriptions..."STA.ROSA NEJ BLLM NO.177, PB-03-000046 DENR III 2014".

ACCESS:
The monument is located along the right side of the barangay road going to Brgy. Inspector Proper. It is 250 meters after the Brgy. Hall of Inspector and is 800 meters from the Sta. Rosa-Tarlac Road.

SURVEYED/ DESCRIBED BY:	GeoIDEx	DATE ESTABLISHED:	April 28-May 17, 2014
--------------------------------	----------------	--------------------------	------------------------------

PHOTO / SKETCH



For updates please rectify and return to DENR R3 LMS Office or fax to (045) 455-3402.